


FIG. 1



FOOTPRINT" 6125T00T

FIG. 2






FIG. 3A**FIG. 3B**

FIG. 4




FIG. 5




FIG. 6




FIG. 7A




FIG. 7B




FIG. 8




FIG. 9A

BEFORE CMP




FIG. 9B

AFTER CMP




FIG. 10A




FIG. 10B




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15A




FIG. 15B




FIG. 16

